

Lift /Ramp Road Call Report
June 1, 2021 – July 2, 2021

Coach Series	Type	Date	Coach # <i>*Pre-trip failure</i>	Line #	Operator Length of Service	Problem Description	Problem Found <i>* Indicates Chargeable</i>	Pax Received Ride?
1300 (Lift U)	Ramp	6/16/21	1350	18	60+ mos.	Operator stated that the coach would not go into gear. Shop notified.	Adjusted ramp*	1344
1300 (Lift U)	Ramp	6/17/21	1351	36	25-60 mos.	Ramp not working	Repaired wheelchair rails.*	1581
1400 (Lift U)	Ramp	6/8/21	1406	56	60+ mos.	Ramp won't deploy	Loose change and debris in ramp track/cleared	1419
6100 (Lift U)	Ramp	6/30/21	6146	F	60+ mos.	Wheelchair light won't go off/coach won't go into gear. Problem with wheelchair sensor.	Changed proxie switch.*	6154

Operator Length of Service Totals:

0-6 Mos.: 0 Operator;	7-12 Mos.: 0 Operators;	13-24 Mos.: 0 Operators;	25-60 Mos.: 1 Operators;	60+ Mos.: 3 Operators
(15)	(112)	(215)	(418)	(742)

Series	Year Added	Type	Qty
1000	2003	True Low Floor Standard (40 ft.)	30
1200	2008	True Low Floor Standard (40 ft.) <Van Hool>	27
1300	2012	Standard Low Floor (40 ft) Gillig	65
1400	2014	Standard Low Floor (40 ft) Gillig	68
1500	2016-2017	Standard Low Floor (40 ft) Gillig	90
1600	2018	Standard Low Floor (40 ft) Gillig	35
2100	2006-2009	Suburban Articulated	33
2200	2013, 2017	Standard Low Floor (60 ft.) <New Flyer>	52
2300	2018	BRT Bus, (60 ft.) <New Flyer Xcelsior>	27
3500	2015	Eldorado Small Transit Vehicle	10
5000	2006	Low Floor Standard (30 ft.)	51
5100	2009	Low Floor Standard (30 ft.)	39
6000	2000-2003	Commuter Coaches <MCI>	36
6100	2014	Commuter Coaches (40 ft.) <Gillig>	54
6200	2018	Low Floor Double Deckers (42.5 ft.)	15
7000	2018	Fuel Cell (40 ft) New Flyer	10
8000	2019	Battery Electric (60 ft.) <New Flyer>	5
FC	2010	Fuel Cell Standard (40 ft.)	11
<i>*Total Revenue Vehicle – Active</i>			635

*Some buses are not active or maybe replacements