

Lift /Ramp Road Call Report
April 1, 2025 – April 30, 2025

Coach Series	Type	Date	Coach # <i>*Pre-trip failure</i>	Line #	Operator Length of Service	Problem Description	Problem Found <i>* Indicates Chargeable</i>	Pax Received Ride?
1300 (Lift U)	Ramp	4/28/25	1355	52	25-60 mos.	Ramp will not deploy	Replaced drive chain*	7035
1400 (Lift U)	Ramp	4/3/25	1433	97	60+ mos.	Ramp will not deploy	Ramp controller bad*	1604
1500 (Lift U)	Ramp	4/2/25	1526	71	60+ mos.	Ramp light comes on while driving	Cleaned debris off of ramp	1464
1700 (Lift U)	Ramp	4/15/25	1701	90	25-60 mos.	Ramp will not deploy	Repaired stow latch solenoid*	1706

Operator Length of Service Totals:

0-6 Mos.: **0** Operator; 7-12 Mos.: **0** Operators; 13-24 Mos.: **0** Operators; 25-60 Mos.: **2** Operators; 60+ Mos.: **2** Operators
 (104) (98) (201) (399) (462)

Series	Year Added	Type	Qty
1300	2012	Standard Low Floor (40 ft) Gillig	65
1400	2014	Standard Low Floor (40 ft) Gillig	68
1500	2016-2017	Standard Low Floor (40 ft) Gillig	91
1600	2018, 2022	Standard Low Floor (40 ft) Gillig	85
1700	2024	Gillig, Urban (40 ft)	50
2190	2009	Suburban Articulated Van HOOL (60 ft.)	9
2200	2013, 2017	Standard Low Floor (60 ft.) <New Flyer>	51
2300	2018	BRT Bus, (60 ft.) <New Flyer Xcelsior>	27
3500	2014	Eldorado, Flex (26 ft.)	6
5100	2009	Low Floor Standard (30 ft.)	10
6100	2014	Commuter Coaches (40 ft.) <Gillig>	54
6200	2018	Low Floor Double Deckers (42.5 ft.)	15
6300	2022	MCI Transbay (45 ft.)	36
7000	2018, 2022	Fuel Cell (40 ft) New Flyer	30
8000	2019, 2021, 2022	Battery Electric (40 ft.) <New Flyer> & Gillig	28
<i>*Total Revenue Vehicle – Active</i>			625

*Some buses are not active or maybe replacements