

REPORT 20-099
Lift /Ramp Road Call Report
January 5, 2020 – February 1, 2020

Coach Series	Type	Date	Coach #	Line #	Operator Length of Service	Problem Reported	Problem Found * <i>Indicates Chargeable</i>	Pax Received Ride?
1000 (<i>VH-Ricon</i>)	Ramp	1/19/20	1101	97	60+ mos.	Door won't close	Changed W/C door lock*	1101
1300 (<i>Lift U</i>)	Ramp	1/30/20	1343	6	60+ mos.	Bad proximity switch	changed proximity switch*	1574
1500 (<i>Lift U</i>)	Ramp	1/16/20	1525	72R	60+ mos.	Ramp not working	Ramp repaired*	1210
2200 (<i>New Flyer</i>)	Ramp	1/27/20	2216	NL	60+ mos.	Chains broke on ramp	Replaced lift chain*	1430
2200 (<i>New Flyer</i>)	Ramp	1/13/20	2219	40	0-6 mos.	Chains broke on ramp	Repaired lift chain*	1023
5000 (<i>VH-Ricon</i>)	Ramp	1/28/20	5029	93	60+ mos.	Ramp won't lay flat	adjusted ramp*	5138

Operator Length of Service Totals:

0-6 Mos: **1** Operator; 7-12 Mos: **0** Operators; 13-24 Mos: **0** Operators; 25-60 Mos: **0** Operators; 60+ Mos: **5** Operators
 (37) (33) (104) (356) (857)

Series	Year Added	Type	Qty
1000	2003	True Low Floor Standard (40 ft.)	36
1200	2008	True Low Floor Standard (40 ft.) <Van Hool>	27
1300	2012	Standard Low Floor (40 ft) Gillig	65
1400	2014	Standard Low Floor (40 ft) Gillig	68
1500	2016-2017	Standard Low Floor (40 ft) Gillig	90
1600	2018	Standard Low Floor (40 ft) Gillig	35
2100	2006-2009	Suburban Articulated	33
2200	2013, 2017	Standard Low Floor (60 ft.) <New Flyer>	52
2300	2018	BRT Bus, (60 ft.) <New Flyer Xcelsior>	27
3500	2015	Eldorado Small Transit Vehicle	10
5000	2006	Low Floor Standard (30 ft.)	51
5100	2009	Low Floor Standard (30 ft.)	39
6000	2000-2003	Commuter Coaches <MCI>	36
6100	2014	Commuter Coaches (40 ft.) <Gillig>	54
6200	2018	Low Floor Double Deckers (42.5 ft.)	15
7000	2018	Fuel Cell (40 ft) New Flyer	10
FC	2010	Fuel Cell Standard (40 ft.)	11
<i>*Total Revenue Vehicle – Active</i>			635

*Some buses are not active or maybe replacements