
Lift /Ramp Road Call Report April 1, 2023 – April 30, 2023

Coach Series	Type	Date	Coach # *Pre-trip failure	Line #	Operator Length of Service	Problem Description	Problem Found * Indicates Chargeable	Pax Received Ride?
1400 (Lift U)	Ramp	4/26/23	1454	652	60+ mos.	Ramp won't close	Coin removed from	
							locking ring.	
1500 (Lift U)	Ramp	4/24/23	1562	51B	60+ mos.	Ramp not working	Repaired ramp in operation	
1600 (Lift U)	Ramp	4/26/23	1649	36	60+ mos.	Ramp not working	Repaired Connector*	
6100 (Lift U)	Ramp	4/25/23	6118	NL	60+ mos.	Ramp won't lay flat	Lift damaged by the wheelchair. Replaced pull ring*	

Operator Length of Service Totals:



Series	Year Added	Туре	Qty			
1000	2003	True Low Floor Standard (40 ft.)	20			
1200	2008	True Low Floor Standard (40 ft.) <van hool=""></van>	27			
1300	2012	Standard Low Floor (40 ft) Gillig	65			
1400	2014	Standard Low Floor (40 ft) Gillig	68			
1500	2016-2017	Standard Low Floor (40 ft) Gillig	90			
1600	2018	Standard Low Floor (40 ft) Gillig	35			
2100	2006-2009	Suburban Articulated	33			
2200	2013, 2017	Standard Low Floor (60 ft.) <new flyer=""></new>	52			
2300	2018	BRT Bus, (60 ft.) <new flyer="" xcelsior=""></new>	27			
3500	2015	Eldorado Small Transit Vehicle	10			
5000	2006	Low Floor Standard (30 ft.)	51			
5100	2009	Low Floor Standard (30 ft.)	39			
6000	2000-2003	Commuter Coaches <mci></mci>	36			
6100	2014	Commuter Coaches (40 ft.) <gillig></gillig>	54			
6200	2018	Low Floor Double Deckers (42.5 ft.)	15			
7000	2018	Fuel Cell (40 ft) New Flyer	10			
8000	2019	Battery Electric (60 ft.) <new flyer=""></new>	5			
FC	2010	Fuel Cell Standard (40 ft.)	11			
*Total Revenue Vehicle – Active						

^{*}Some buses are not active or maybe replacements