

**Lift /Ramp Road Call Report
January 2, 2021 – February 1, 2021**

Coach Series	Type	Date	Coach # *Pre-trip failure	Line #	Operator Length of Service	Problem Description	Problem Found * Indicates Chargeable	Pax Received Ride?
1300 (Lift U)	Ramp	1/25/21	1308	20	60+ mos.	Ramp not working	Ramp platform bent	1329
1500 (Lift U)	Ramp	1/20/21	1537	70	60+ mos.	Coach stalled in middle of street, wheelchair lift alarm going off.	CHG Ramp Module*	1550
2300 (BRT New Flyer)	Ramp	1/28/21	2306	1T	25-60 mos.	Door won't close	Adjust ramp platformed*	2310

Operator Length of Service Totals:

0-6 Mos: **0** Operator; 7-12 Mos: **0** Operators; 13-24 Mos: **0** Operators; 25-60 Mos: **1** Operators; 60+ Mos: **2** Operators
(52) (128) (89) (411) (825)

Series	Year Added	Type	Qty
1000	2003	True Low Floor Standard (40 ft.)	30
1200	2008	True Low Floor Standard (40 ft.) <Van Hool>	27
1300	2012	Standard Low Floor (40 ft) Gillig	65
1400	2014	Standard Low Floor (40 ft) Gillig	68
1500	2016-2017	Standard Low Floor (40 ft) Gillig	90
1600	2018	Standard Low Floor (40 ft) Gillig	35
2100	2006-2009	Suburban Articulated	33
2200	2013, 2017	Standard Low Floor (60 ft.) <New Flyer>	52
2300	2018	BRT Bus, (60 ft.) <New Flyer Xcelsior>	27
3500	2015	Eldorado Small Transit Vehicle	10
5000	2006	Low Floor Standard (30 ft.)	51
5100	2009	Low Floor Standard (30 ft.)	39
6000	2000-2003	Commuter Coaches <MCI>	36
6100	2014	Commuter Coaches (40 ft.) <Gillig>	54
6200	2018	Low Floor Double Deckers (42.5 ft.)	15
7000	2018	Fuel Cell (40 ft) New Flyer	10
8000	2019	Battery Electric (60 ft.) <New Flyer>	5
FC	2010	Fuel Cell Standard (40 ft.)	11
<i>*Total Revenue Vehicle – Active</i>			635

*Some buses are not active or maybe replacements